

**Gonzales County Underground Water Conservation District
Mitigation Fund Manager's Report
August 2016**

On August 9th, I met B&S Driller at the Mr. Victor Vana well to measure depth of wells. Then I went to Ottine and met Mr. Dean Davis to look at 8 possible Carrizo wells. One well had quit flowing.

On August 10th, I met B&S at the Vana well to remove well head with troch. Most likely a Sparta well.

On August 19th, I met Mr. David Kuntschit to discuss mitigation on a well that quit flowing.

On August 22nd, I met B&S and Mr. James Miller to discuss work needed on well.

